




# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Tuesday, April 7, 2020  
Accumulation in Inches

L a k e E r i e



# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Tuesday, April 7, 2020

Site Location	Peak Accumulation (inches)						
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute	
Beachwood	0.49	0.46	0.46	0.46	0.32	0.19	
Brecksville	0.63	0.40	0.40	0.40	0.34	0.22	
Brook Park	1.06	0.80	0.80	0.80	0.67	0.38	
Cleveland Industrial Pkwy	0.65	0.41	0.41	0.40	0.26	0.13	
Dille Ave PS	0.66	0.54	0.54	0.54	0.21	0.11	
Division Ave PS	0.69	0.52	0.52	0.52	0.26	0.14	
Easterly WWTP	0.32	0.25	0.25	0.25	0.15	0.10	
Independence	0.64	0.45	0.45	0.45	0.38	0.16	
James Rhodes HS	0.69	0.44	0.44	0.40	0.23	0.12	
Jennings PS	1.21	1.03	1.03	0.96	0.45	0.25	
Macedonia	0.55	0.30	0.30	0.30	0.27	0.15	
Maple Heights	0.65	0.50	0.50	0.47	0.26	0.12	
Mary Street PS	0.72	0.57	0.57	0.56	0.24	0.12	
Mayfield Heights	0.30	0.24	0.24	0.24	0.16	0.08	
Moreland Hills	1.19	1.12	1.12	1.12	0.60	0.26	
North Olmsted	1.20	0.88	0.88	0.88	0.71	0.39	
North Royalton	0.57	0.33	0.33	0.33	0.26	0.11	
Oakwood	0.58	0.36	0.36	0.36	0.30	0.15	
Olmsted Falls	0.95	0.66	0.66	0.66	0.56	0.26	
Parma	0.72	0.49	0.49	0.49	0.42	0.25	
Richfield	0.65	0.33	0.33	0.33	0.32	0.13	
Shaker Heights	0.74	0.65	0.65	0.65	0.35	0.18	
South Euclid	0.29	0.23	0.23	0.23	0.11	0.05	
Southerly WWTC	0.79	0.62	0.62	0.56	0.29	0.20	
Strongsville C WWTP	0.77	0.50	0.50	0.50	0.39	0.20	
Strongsville Foltz	0.72	0.41	0.41	0.41	0.36	0.18	
University Heights	0.44	0.41	0.41	0.41	0.28	0.14	
Wade Park	0.44	0.40	0.40	0.40	0.26	0.14	
Westlake	0.88	0.63	0.63	0.62	0.41	0.22	

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

**WO Number:** 200408-0002      **Category:** SSOs  
**Status:** New Work Order      **Problem:** Excessive Rainfall  
**Status Date:** 4/8/2020 12:00 pm      **Main Task:** Inspection  
**Asset:** SSO 102  
**Location:** 2225 NOBLE ROAD

**Cause:**      **Assigned By:**  
**Assigned Crew:**      **Assigned Date:** 4/7/2020 7:00 AM  
**Supervisor:** Jackson, Jeff      **Start Date:** 4/9/2020 8:00 AM      Override  
**Lead Worker:** Mc Coy, Sam      **End Date:** 4/10/2020      Notifications  
**Priority:** High       Problem   
**Account #:**       Overdue   
**Proj No - Acct:**      **Project ID:**       Lead Worker   
**Project:**      **Project Name:**       Task   
**Reason:**       Supervisor   
**Received By:**       Hard Lock WO   
**Inspected By:**

**Request Comments for Work Order**  
EXCESSIVE RAINFALL 0.44 INCHES OF RAIN

**Location**  
**Department:** Sewer Collection  
**Division:** Sewer Collection  
**Sub-Division:**  
**Area:**  
**Sub-Area:**  
**Owner:**  
**Location:**  
**Classification:**  
**Maintenance Zone:**      **Alternate Zone:**

**Comments for Crew**  
RESET BLOCK

Work Order Locations		
<u>Address</u>	<u>Address 2</u>	
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
COVENTRY SOUTH OF FAIRMOUNT		
2,220,178.73142348	666,876.97731304	Doan Brook
COVENTRY/CEDAR		
2,220,516.67923839	669,679.88509305	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH

\* A 'Hidden' field indicates permission to view the secured field is turned off.

## Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

FAIRMOUNT AT LEE		
2,224,647.69623882	664,467.25017713	Doan Brook
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
2,225,617.27960148	665,510.97315531	
2,225,612.24483465	665,508.19560181	
2,226,741.98076415	679,430.76519755	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	
2,226,592.54503940	679,418.74159955	

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

Work Order Assets							
Object Type	Description 1			Description 2			
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					2225 NOBLE ROAD		
SSO 102						3	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	
Sewer Control Valve					COVENTRY SOUTH OF FAIRMOUNT		
SSO 426						13	
Sewer Control Valve					COVENTRY/CEDAR		
SSO 93						27	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT LEE		
CH-08						41	
Sewer Control Valve					LEE RD. & SUPERIOR AVE.		
DV-11						9	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Structure							
ST16ZBTK0						2992	
Sewer Structure							
SA16AFWE0						3851	
Sewer Structure							
ST16ZJRC0						4020	
Sewer Structure							
SA16AQD0						4987	
Sewer Structure							
SA16AQQC0						3745	
Sewer Structure							
ST16ZJRB0						4416	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	SSO A CH-01 FAIRMOUNT AND NORTH WOODLAND (3041)	<input type="checkbox"/>	Sound	4/9/2020/	
2	SSO A CH-02 FAIRMOUNT AND NORTH WOODLAND (3026)	<input type="checkbox"/>	Sound	4/9/2020/	
3	SSO A CH-03 FAIRMOUNT AT WELLINGTON	<input type="checkbox"/>		4/9/2020/	
4	SSO A CH-04 FAIRMOUNT AT DARTMOOR	<input type="checkbox"/>	Sound	4/9/2020/	
5	SSO A CH-32 FAIRMOUNT AT ARLINGTON	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
6	SSO A CH-33 FAIRMOUNT AND FAIRFAX (SOUTH SIDE)	<input type="checkbox"/>	Not Sound	4/9/2020/	
Can't reset still surcharging					
7	SSO A CH-35 2393 COVENTRY W OF FAIRMOUNT	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
8	SSO A CH-36 NORTH PARK AT COVENTRY	<input type="checkbox"/>	Sound	4/9/2020/	
9	SSO A CH-37 FAIRFAX AND NORTH PARK	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
10	SSO A CH-38 FAIRMOUNT AT MARLBORO	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
11	SSO A CH-39 3012 NORTH WOODLAND	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
12	SSO A CH-45 FAIRMOUNT IN THE ISLAND	<input type="checkbox"/>	Sound	4/9/2020/	
13	SSO A CH-49 FAIRMOUNT EAST OF CHURCH	<input type="checkbox"/>	Sound	4/9/2020/	
14	SSO A CH-50 SCARBOROUGH AND LAMBERTON	<input type="checkbox"/>	Not Sound	4/9/2020/	
Reset block					
15	SSO B CH-09 BRADFORD AND LEE	<input type="checkbox"/>	Not Sound	4/9/2020/	
Can't reset block still surcharging					
16	SSO B CH-10 HAMPSHIRE LANE AT MAYFIELD 18"	<input type="checkbox"/>	Sound	4/10/2020/	
17	SSO B CH-11 HAMPSHIRE LANE AT MAYFIELD 36"	<input type="checkbox"/>	Sound	4/10/2020/	
18	SSO B CH-13 HAMPSHIRE LANE AT EUCLID HTS. BLVD	<input type="checkbox"/>	Not Sound	4/10/2020/	
Reset block					
19	SSO B CH-17 1685 CUMBERLAND	<input type="checkbox"/>	Sound	4/9/2020/	
20	SSO B CH-22 2225 NOBLE ROAD	<input type="checkbox"/>	Sound	4/10/2020/	
21	SSO B CH-25 CUMBERLAND AND SOMERTON	<input type="checkbox"/>	Sound	4/9/2020/	
22	SSO B CH-26 EUCLID HTS. BLVD. AND CUMBERLAND	<input type="checkbox"/>	Sound	4/9/2020/	
23	SSO B CH-27 QUILLIAMS AND RANDOLPH	<input type="checkbox"/>	Sound	4/10/2020/	
24	SSO B CH-28 EUCLID HTS. BLVD. AND LEE RD.	<input type="checkbox"/>	Not Sound	4/10/2020/	
Reset block					
25	SSO B CH-51 ATHERSTONE AND LANGTON	<input type="checkbox"/>	Sound	4/10/2020/	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

26	SSO C CH-12 LEE AND SUPERIOR	<input type="checkbox"/>	Not Sound	4/10/2020/
Reset block				
27	SSO C CH-14 DERBYSHIRE AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Not Sound	4/10/2020/
Reset block				
28	SSO C CH-15 COVENTRY AND CEDAR	<input type="checkbox"/>	Sound	4/10/2020/
29	SSO C CH-23 2828 BERKSHIRE EAST OF COVENTRY	<input type="checkbox"/>	Sound	4/10/2020/
30	SSO C CH-24 3003 EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/10/2020/
31	SSO C CH-30 SOUTH TAYLOR NORTH OF SUPERIOR	<input type="checkbox"/>	Not Sound	4/10/2020/
Reset block				
32	SSO C CH-42 12537 CEDAR ROAD	<input type="checkbox"/>	Sound	4/10/2020/
33	SSO C CH-46 EDGEHILL AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Not Sound	4/10/2020/
Reset block				
34	SSO C CH-47 2528 STRATFORD	<input type="checkbox"/>	Sound	4/9/2020/
35	SSO C CH-52 EDDINGTON ROAD NORTH OF AVONDALE	<input type="checkbox"/>	Sound	4/9/2020/
36	SSO C CH-54 2806 FAIRMOUNT	<input type="checkbox"/>	Sound	4/10/2020/
37	SSO A CH-5 FAIRMOUNT AND SHELBURNE	<input type="checkbox"/>	Sound	4/10/2020/
38	SSO A CH- 6 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Not Sound	4/10/2020/
Reset block				
39	SSO A CH-07 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Sound	4/10/2020/
40	SSO C CH-50 3293 FENLEY	<input type="checkbox"/>		4/10/2020/
There is no 3293 Fenley the lowest address is 3500 Fenley				
41	SSO B CH-57 E MONMOUTH W OF DARTMOOR	<input type="checkbox"/>	Sound	4/10/2020/
42	SSO B CH-58 E MONMOUTH AT EXETER	<input type="checkbox"/>	Sound	4/10/2020/
43	SSO B CH-59 3427 THORNE RD	<input type="checkbox"/>	Sound	4/10/2020/
44	SSO B CH-60 3415 THORNE ROAD	<input type="checkbox"/>	Sound	4/10/2020/
45	SSO C CH-61 2600 HAMPSHIRE ROAD	<input type="checkbox"/>	Sound	4/10/2020/
46	SSO CH-56 MEADOWBROOK AND LEE	<input type="checkbox"/>		4/10/2020/
Could not find the right manhole				

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

Tasks/Resources						
<b>SWCT26 Inspection</b>						
<b>Crew:</b>	<b>Status:</b>	<b>*Cal'c UC:</b> \$8.89	<b>*Task Cost:</b> \$409.12	<b>Start Dt:</b> 4/9/2020		
<b>Supervisor:</b>	<b>UOM:</b> Each	<b># of Units:</b> 46.00	<b>*Unit Cost:</b> \$0.00	<b>End Dt:</b>		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
28056 Palmisano, Anthony	Hours	4.00	\$80.24		4/9/2020	
22394 Cardarella, Joe	Hours	4.00	\$86.16		4/9/2020	
40151 Mc Coy, Sam	Hours	8.00	\$135.52		4/9/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		4/9/2020	
<b>Task Comment:</b> 0.44 INCHES OF RAIN						

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
<b>Projected Complete:</b>	<b>Lock:</b> <input type="checkbox"/>	<b>WO Duration</b>	8.00	0.00	0.00
<b>Repair Type:</b>		<b>Labor Hours</b>	16.00	0.00	0.00
<b>Subcontractor:</b>		<b>Labor Costs</b>	\$301.92	\$0.00	\$0.00
<b>Profit Center:</b>		<b>Material Costs</b>	0.00	0.00	0.00
		<b>Fluids Costs</b>	0.00	0.00	0.00
<b>Quantity:</b> 0.00	<b>Lock:</b> <input type="checkbox"/>	<b>Equipment Costs</b>	107.20	0.00	0.00
<b>Unit of Measure:</b>		<b>Contractor Costs</b>	0.00	0.00	0.00
<b>*Unit Cost:</b> \$0.00		<b>Misc. Costs</b>	0.00	0.00	0.00
<b>WO Hours:</b> 0.00		<b>Total Costs</b>	<b>\$409.12</b>	<b>\$0.00</b>	<b>\$0.00</b>
<b>Use Task Info:</b>			True	True	

Billing		
<b>Billed Party</b>		
<b>Customer ID:</b>	<b>Customer Number:</b>	
<b>Customer Name:</b>	<b>Last Name:</b>	
<b>Address:</b>	<b>Phone:</b>	<b>Cell #:</b>
<b>City:</b>	<b>Fax #:</b>	
<b>State:</b>	<b>E-mail:</b>	
<b>Zip:</b>		
<b>Billing Data</b>		
<b>Contact Name:</b>	<b>*Billing Amount:</b>	<b>Billing Required:</b> <input type="checkbox"/>
<b>Invoice Number:</b>	<b>Date Bill Sent:</b>	<b>Billing Processed:</b> <input type="checkbox"/>
<b>Incoming Account #:</b>	<b>Payment Received:</b>	<b>Imported to Financials:</b> <input type="checkbox"/>
	<b>Payment Method:</b>	

Associated PMs		
PM Code and Description		Closed
SSO-101 SSO INSPECTION FORM		<input checked="" type="checkbox"/>

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-101 - SSO INSPECTION FORM	aferrone	4/8/2020	12:00 PM
Supervisor Notification	Email Queued Successfully!	aferrone	4/8/2020	12:00 PM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	4/8/2020	12:01 PM

\* A 'Hidden' field indicates permission to view the secured field is turned off.

# Work Order Detail Report

4/10/2020

SSO INSPECTION 4-7-2020 0.44 INCHES OF RAIN

2:53 PM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30:	<input type="checkbox"/>
Test Performed Throug	Appointment Time:		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	WO User 22:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Siet		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 4/8/2020	PM Trigger:	Rec #: 5354




# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Monday, April 13, 2020

Accumulation in Inches

L a k e E r i e



**Northeast Ohio Regional Sewer District**

Daily Precipitation Report

Monday, April 13, 2020

Site Location	Peak Accumulation (inches)						
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute	
Beachwood	0.57	0.42	0.32	0.21	0.08	0.05	
Brecksville	0.47	0.27	0.23	0.11	0.06	0.03	
Brook Park	0.30	0.20	0.12	0.09	0.04	0.02	
Cleveland Industrial Pkwy	0.30	0.20	0.11	0.08	0.04	0.02	
Dille Ave PS	0.28	0.17	0.12	0.05	0.03	0.01	
Division Ave PS	0.27	0.17	0.10	0.07	0.04	0.02	
Easterly WWTP	n/a	n/a	n/a	n/a	n/a	n/a	
Independence	0.55	0.37	0.28	0.17	0.08	0.04	
James Rhodes HS	0.30	0.19	0.13	0.07	0.03	0.02	
Jennings PS	0.38	0.24	0.15	0.07	0.03	0.02	
Macedonia	0.50	0.30	0.22	0.10	0.05	0.03	
Maple Heights	0.47	0.33	0.24	0.16	0.06	0.04	
Mary Street PS	0.29	0.17	0.11	0.07	0.03	0.02	
Mayfield Heights	0.61	0.44	0.33	0.22	0.10	0.05	
Moreland Hills	0.61	0.44	0.28	0.16	0.08	0.03	
North Olmsted	0.39	0.28	0.17	0.11	0.04	0.02	
North Royalton	0.46	0.30	0.22	0.11	0.07	0.04	
Oakwood	0.62	0.37	0.23	0.16	0.07	0.03	
Olmsted Falls	0.37	0.29	0.20	0.13	0.05	0.03	
Parma	0.40	0.24	0.17	0.09	0.05	0.03	
Richfield	0.54	0.31	0.22	0.14	0.07	0.04	
Shaker Heights	0.47	0.33	0.26	0.14	0.07	0.03	
South Euclid	0.45	0.32	0.28	0.13	0.08	0.03	
Southerly WWTC	0.35	0.23	0.18	0.09	0.04	0.02	
Strongsville C WWTP	0.34	0.20	0.12	0.09	0.04	0.02	
Strongsville Foltz	0.35	0.23	0.14	0.09	0.03	0.02	
University Heights	0.45	0.33	0.29	0.17	0.07	0.03	
Wade Park	0.34	0.23	0.15	0.08	0.05	0.03	
Westlake	0.31	0.23	0.15	0.09	0.04	0.02	

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

**WO Number:** 200414-0002      **Category:** SSOs  
**Status:** New Work Order      **Problem:** Excessive Rainfall  
**Status Date:** 4/14/2020 12:08 pm      **Main Task:** Inspection

**Asset:** SSO 102  
**Location:** 2225 NOBLE ROAD

**Cause:**      **Assigned By:**  
**Assigned Crew:**      **Assigned Date:** 4/13/2020 7:00 AM  
**Supervisor:** Jackson, Jeff      **Start Date:** 4/14/2020 8:00 AM      Override  
**Lead Worker:** Cardarella, Joe      **End Date:** 4/15/2020      Notifications  
**Priority:** High       Problem  
**Account #:**       Overdue  
**Proj No - Acct:**      **Project ID:**       Lead Worker  
**Project:**      **Project Name:**       Task  
**Reason:**       Supervisor  
**Received By:**       Hard Lock WO  
**Inspected By:**

**Request Comments for Work Order**  
 EXCESSIVE RAIN 0.45"

**Location**  
**Department:** Sewer Collection      **Comments for Crew**  
**Division:** Sewer Collection      RESET BLOCK  
**Sub-Division:**  
**Area:**  
**Sub-Area:**  
**Owner:**  
**Location:**  
**Classification:**  
**Maintenance Zone:**      **Alternate Zone:**

Work Order Locations		
Address		Address 2
X Coord	Y Coord	General Location
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
COVENTRY SOUTH OF FAIRMOUNT		
2,220,178.73142348	666,876.97731304	Doan Brook
COVENTRY/CEDAR		
2,220,516.67923839	669,679.88509305	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH

\* A 'Hidden' field indicates permission to view the secured field is turned off.

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

FAIRMOUNT AT LEE		
2,224,647.69623882	664,467.25017713	Doan Brook
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
2,225,617.27960148	665,510.97315531	
2,225,612.24483465	665,508.19560181	
2,226,741.98076415	679,430.76519755	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	
2,226,592.54503940	679,418.74159955	

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

Work Order Assets						
Object Type	Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID
						Completed
Sewer Control Valve					2225 NOBLE ROAD	
SSO 102						3
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103						19
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD	
SSO 104						15
Sewer Control Valve					COVENTRY SOUTH OF FAIRMOUNT	
SSO 426						13
Sewer Control Valve					COVENTRY/CEDAR	
SSO 93						27
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	
SSO 110						44
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	
SSO 111						46
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	
SSO 112						7
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91						20
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89						34
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	
CH-04						5
Sewer Control Valve					FAIRMOUNT AT LEE	
CH-08						41
Sewer Control Valve					LEE RD. & SUPERIOR AVE.	
DV-11						9
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87						33
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99						6
Sewer Structure						
ST16ZBTK0						2992
Sewer Structure						
SA16AFWE0						3851
Sewer Structure						
ST16ZJRC0						4020
Sewer Structure						
SA16AQD0						4987
Sewer Structure						
SA16AQQC0						3745
Sewer Structure						
ST16ZJRB0						4416

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	SSO A CH-01 FAIRMOUNT AND NORTH WOODLAND (3041)	<input type="checkbox"/>	Sound	4/15/2020/12:57 pm	
2	SSO A CH-02 FAIRMOUNT AND NORTH WOODLAND (3026)	<input type="checkbox"/>	Sound	4/15/2020/12:50 pm	
3	SSO A CH-03 FAIRMOUNT AT WELLINGTON	<input type="checkbox"/>	Sound	4/15/2020/ 1:35 pm	
4	SSO A CH-04 FAIRMOUNT AT DARTMOOR	<input type="checkbox"/>	Not Sound	4/15/2020/10:03 am	
String off board					
5	SSO A CH-32 FAIRMOUNT AT ARLINGTON	<input type="checkbox"/>	Sound	4/15/2020/ 1:02 pm	
6	SSO A CH-33 FAIRMOUNT AND FAIRFAX (SOUTH SIDE)	<input type="checkbox"/>	Not Sound	4/15/2020/12:35 pm	
Reset block					
7	SSO A CH-35 2393 COVENTRY W OF FAIRMOUNT	<input type="checkbox"/>	Not Sound	4/15/2020/12:19 pm	
Lid flipped before I could reset need help					
8	SSO A CH-36 NORTH PARK AT COVENTRY	<input type="checkbox"/>	Sound	4/15/2020/12:43 pm	
9	SSO A CH-37 FAIRFAX AND NORTH PARK	<input type="checkbox"/>	Sound	4/15/2020/12:40 pm	
10	SSO A CH-38 FAIRMOUNT AT MARLBORO	<input type="checkbox"/>	Sound	4/15/2020/ 1:42 pm	
11	SSO A CH-39 3012 NORTH WOODLAND	<input type="checkbox"/>	Sound	4/15/2020/12:49 pm	
12	SSO A CH-45 FAIRMOUNT IN THE ISLAND	<input type="checkbox"/>	Sound	4/15/2020/10:25 am	
13	SSO A CH-49 FAIRMOUNT EAST OF CHURCH	<input type="checkbox"/>	Sound	4/15/2020/10:35 am	
14	SSO A CH-50 SCARBOROUGH AND LAMBERTON	<input type="checkbox"/>	Sound	4/15/2020/ 9:46 am	
15	SSO B CH-09 BRADFORD AND LEE	<input type="checkbox"/>	Sound	4/15/2020/ 9:29 am	
16	SSO B CH-10 HAMPSHIRE LANE AT MAYFIELD 18"	<input type="checkbox"/>	Sound	4/14/2020/ 1:09 pm	
17	SSO B CH-11 HAMPSHIRE LANE AT MAYFIELD 36"	<input type="checkbox"/>	Sound	4/14/2020/ 1:11 pm	
18	SSO B CH-13 HAMPSHIRE LANE AT EUCLID HTS. BLVD	<input type="checkbox"/>	Sound	4/14/2020/ 1:18 pm	
19	SSO B CH-17 1685 CUMBERLAND	<input type="checkbox"/>	Sound	4/15/2020/ 8:42 am	
20	SSO B CH-22 2225 NOBLE ROAD	<input type="checkbox"/>	Sound	4/14/2020/	
21	SSO B CH-25 CUMBERLAND AND SOMERTON	<input type="checkbox"/>	Sound	4/15/2020/ 8:36 am	
22	SSO B CH-26 EUCLID HTS. BLVD. AND CUMBERLAND	<input type="checkbox"/>	Sound	4/15/2020/ 8:33 am	
23	SSO B CH-27 QUILLIAMS AND RANDOLPH	<input type="checkbox"/>	Sound	/12:23 pm	
24	SSO B CH-28 EUCLID HTS. BLVD. AND LEE RD.	<input type="checkbox"/>	Not Sound	4/15/2020/ 8:53 am	
Reset block					
25	SSO B CH-51 ATHERSTONE AND LANGTON	<input type="checkbox"/>	Sound	4/14/2020/	
26	SSO C CH-12 LEE AND SUPERIOR	<input type="checkbox"/>	Sound	4/15/2020/ 8:57 am	
27	SSO C CH-14 DERBYSHIRE AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/14/2020/ 1:22 pm	
28	SSO C CH-15 COVENTRY AND CEDAR	<input type="checkbox"/>	Sound	4/14/2020/ 1:56 pm	
29	SSO C CH-23 2828 BERKSHIRE EAST OF COVENTRY	<input type="checkbox"/>	Sound	4/15/2020/ 8:13 am	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

30	SSO C CH-24 3003 EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/15/2020/ 8:24 am
31	SSO C CH-30 SOUTH TAYLOR NORTH OF SUPERIOR	<input type="checkbox"/>	Sound	4/15/2020/ 9:03 am
32	SSO C CH-42 12537 CEDAR ROAD	<input type="checkbox"/>	Sound	4/15/2020/ 8:05 am
33	SSO C CH-46 EDGEHILL AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/14/2021/
34	SSO C CH-47 2528 STRATFORD	<input type="checkbox"/>	Sound	4/15/2020/ 9:55 am
35	SSO C CH-52 EDDINGTON ROAD NORTH OF AVONDALE	<input type="checkbox"/>	Sound	4/14/2020/ 1:04 pm
Board gone				
36	SSO C CH-54 2806 FAIRMOUNT	<input type="checkbox"/>	Sound	4/15/2020/12:25 pm
37	SSO A CH-5 FAIRMOUNT AND SHELBURNE	<input type="checkbox"/>	Sound	4/15/2020/10:14 am
38	SSO A CH- 6 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Sound	4/15/2020/10:16 am
String is to far down doesn't appear to be moved				
39	SSO A CH-07 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Sound	4/15/2020/10:09 am
40	SSO C CH-50 3293 FENLEY	<input type="checkbox"/>	Sound	/
Reset block				
41	SSO B CH-57 E MONMOUTH W OF DARTMOOR	<input type="checkbox"/>	Sound	4/15/2020/ 9:39 am
42	SSO B CH-58 E MONMOUTH AT EXETER	<input type="checkbox"/>	Sound	4/15/2020/ 9:35 am
43	SSO B CH-59 3427 THORNE RD	<input type="checkbox"/>	Sound	4/14/2020/12:55 pm
44	SSO B CH-60 3415 THORNE ROAD	<input type="checkbox"/>	Sound	4/14/2020/12:52 pm
45	SSO C CH-61 2600 HAMPSHIRE ROAD	<input type="checkbox"/>	Sound	4/14/2020/ 1:16 pm
46	SSO CH-56 MEADOWBROOK AND LEE	<input type="checkbox"/>	Sound	4/15/2020/ 9:22 am

Tasks/Resources						
<b>SWCT26 Inspection</b>						
<b>Crew:</b>	<b>Status:</b>	<b>*Cal'c UC:</b> \$12.83	<b>*Task Cost:</b> \$590.24	<b>Start Dt:</b> 4/15/2020		
<b>Supervisor:</b>	<b>UOM:</b> Each	<b># of Units:</b> 46.00	<b>*Unit Cost:</b> \$0.00	<b>End Dt:</b>		
<b>Employee</b>						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$172.32		4/15/2020	
40151 Mc Coy, Sam	Hours	8.00	\$135.52		4/15/2020	
<b>Equipment</b>						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CAB AND 8 CHASSIS	Hours	16.00	\$282.40		4/15/2020	
<b>Task Comment:</b> EXCESSIVE RAIN 0.45"						

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$307.84	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	282.40	0.00	0.00
Unit of Measure:		Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$590.24	\$0.00	\$0.00
		Use Task Info:	True	True	

**Billing**

<b>Billed Party</b>		
Customer ID:	Customer Number:	
Customer Name:	Last Name:	
Address:		
City:	Phone: Cell #:	
State:	Fax #:	
Zip:	E-mail:	
<b>Billing Data</b>		
Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
	Payment Method:	

**Associated PMs**

PM Code and Description	Closed
SSO-101 SSO INSPECTION FORM	<input checked="" type="checkbox"/>

**Tracking**

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-101 - SSO INSPECTION FORM	aferrone	4/14/2020	12:08 PM
Supervisor Notification	Email Queued Successfully!	aferrone	4/14/2020	12:08 PM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	4/14/2020	12:09 PM

Rates:	Opened At:	Televised: <input type="checkbox"/>
Recieved By:	Pipe Footage Cleaned .	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>
Test Performed Throug	Appointment Time:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	WO User 22:	

**Work Order Detail Report**

4/15/2020

SSO INSPECTION 4-13-2020 0.45" OF RAIN

4:25 PM

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slec
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 4/14/2020	PM Trigger:	Rec #: 5375



**Northeast Ohio Regional Sewer District**

Daily Precipitation Report

Sunday, April 26, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	5-Minute
Beachwood	0.66	0.39	0.26	0.12	0.04
Brecksville	0.85	0.66	0.47	0.18	0.06
Brook Park	0.48	0.44	0.34	0.19	0.06
Cleveland Industrial Pkwy	0.59	0.50	0.36	0.19	0.07
Dille Ave PS	0.52	0.47	0.35	0.17	0.05
Division Ave PS	0.55	0.49	0.35	0.17	0.05
Easterly WWTP	n/a	n/a	n/a	n/a	n/a
Independence	0.63	0.51	0.37	0.16	0.05
James Rhodes HS	0.52	0.44	0.32	0.17	0.06
Jennings PS	0.54	0.48	0.34	0.19	0.06
Macedonia	0.66	0.49	0.37	0.14	0.04
Maple Heights	0.64	0.45	0.30	0.14	0.04
Mary Street PS	0.51	0.46	0.34	0.16	0.05
Mayfield Heights	0.59	0.29	0.18	0.08	0.03
Moreland Hills	0.70	0.45	0.25	0.14	0.07
North Olmsted	0.74	0.60	0.40	0.21	0.07
North Royalton	0.72	0.50	0.34	0.15	0.04
Oakwood	0.59	0.40	0.30	0.12	0.04
Olmsted Falls	0.60	0.56	0.41	0.20	0.06
Parma	0.54	0.46	0.33	0.15	0.05
Richfield	1.04	0.74	0.48	0.19	0.07
Shaker Heights	0.59	0.43	0.29	0.13	0.05
South Euclid	0.57	0.34	0.25	0.12	0.04
Southerly WWTC	0.52	0.44	0.29	0.14	0.05
Strongsville C WWTP	0.54	0.47	0.36	0.18	0.05
Strongsville Foltz	0.71	0.63	0.46	0.21	0.07
University Heights	0.60	0.38	0.25	0.12	0.04
Wade Park	0.43	0.35	0.26	0.12	0.04
Westlake	0.77	0.61	0.42	0.20	0.06

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

**WO Number:** 200427-0002      **Category:** SSOs  
**Status:** New Work Order      **Problem:** Excessive Rainfall  
**Status Date:** 4/27/2020 7:45 am      **Main Task:** Inspection

**Asset:** SSO 102  
**Location:** 2225 NOBLE ROAD

**Cause:**      **Assigned By:**  
**Assigned Crew:**      **Assigned Date:** 11/30/2018 7:00 AM  
**Supervisor:** Jackson, Jeff      **Start Date:** 4/27/2020 8:00 AM      Override  
**Lead Worker:** Cardarella, Joe      **End Date:**      Notifications  
**Priority:** High      **Project ID:**      Problem   
**Account #:**      **Project Name:**      Overdue   
**Proj No - Acct:**      **Project:**      Lead Worker   
**Reason:**      **Project:**      Task   
**Received By:**      **Project:**      Supervisor   
**Inspected By:**      **Project:**      Hard Lock WO

**Request Comments for Work Order**  
 EXCESSIVE RAINFALL 0.60 INCHES OF RAIN

**Location**  
**Department:** Sewer Collection      **Comments for Crew**  
**Division:** Sewer Collection      RESET BLOCK  
**Sub-Division:**  
**Area:**  
**Sub-Area:**  
**Owner:**  
**Location:**  
**Classification:**  
**Maintenance Zone:**      **Alternate Zone:**

Work Order Locations		
Address	Address 2	
X Coord	Y Coord	General Location
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
COVENTRY SOUTH OF FAIRMOUNT		
2,220,178.73142348	666,876.97731304	Doan Brook
COVENTRY/CEDAR		
2,220,516.67923839	669,679.88509305	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

FAIRMOUNT AT LEE		
2,224,647.69623882	664,467.25017713	Doan Brook
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
2,225,617.27960148	665,510.97315531	
2,225,612.24483465	665,508.19560181	
2,226,741.98076415	679,430.76519755	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	
2,226,592.54503940	679,418.74159955	

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

Work Order Assets							
Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					2225 NOBLE ROAD		
SSO 102						3	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	
Sewer Control Valve					COVENTRY SOUTH OF FAIRMOUNT		
SSO 426						13	
Sewer Control Valve					COVENTRY/CEDAR		
SSO 93						27	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT LEE		
CH-08						41	
Sewer Control Valve					LEE RD. & SUPERIOR AVE.		
DV-11						9	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Structure							
ST16ZBTK0						2992	
Sewer Structure							
SA16AFWE0						3851	
Sewer Structure							
ST16ZJRC0						4020	
Sewer Structure							
SA16AQQD0						4987	
Sewer Structure							
SA16AQQC0						3745	
Sewer Structure							
ST16ZJRB0						4416	

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	SS0 A CH-01 FAIRMOUNT AND NORTH WOODLAND (3041)	<input type="checkbox"/>	Sound	4/27/2020/ 1:13 pm	
2	SSO A CH-02 FAIRMOUNT AND NORTH WOODLAND (3026)	<input type="checkbox"/>	Sound	4/27/2020/ 1:09 pm	
3	SSO A CH-03 FAIRMOUNT AT WELLINGTON	<input type="checkbox"/>	Not Sound	4/27/2020/ 1:04 pm	
Reset					
4	SS0 A CH-04 FAIRMOUNT AT DARTMOOR	<input type="checkbox"/>	Sound	4/27/2020/10:20 am	
5	SSO A CH-32 FAIRMOUNT AT ARLINGTON	<input type="checkbox"/>	Sound	4/27/2020/ 1:23 pm	
6	SSO A CH-33 FAIRMOUNT AND FAIRFAX (SOUTH SIDE)	<input type="checkbox"/>	Not Sound	4/27/2020/ 1:39 pm	
Reset					
7	SSO A CH-35 2393 COVENTRY W OF FAIRMOUNT	<input type="checkbox"/>		4/27/2020/	
Lid flipped need 2 people					
8	SSO A CH-36 NORTH PARK AT COVENTRY	<input type="checkbox"/>	Sound	4/27/2020/ 1:45 pm	
9	SSO A CH-37 FAIRFAX AND NORTH PARK	<input type="checkbox"/>	Sound	4/27/2020/	
10	SSO A CH-38 FAIRMOUNT AT MARLBORO	<input type="checkbox"/>	Sound	4/27/2020/ 1:32 pm	
11	SSO A CH-39 3012 NORTH WOODLAND	<input type="checkbox"/>	Sound	4/27/2020/ 1:11 pm	
12	SSO A CH-45 FAIRMOUNT IN THE ISLAND	<input type="checkbox"/>	Sound	4/27/2020/ 1:53 pm	
13	SSO A CH-49 FAIRMOUNT EAST OF CHURCH	<input type="checkbox"/>	Sound	4/27/2020/ 2:02 pm	
14	SSO A CH-50 SCARBOROUGH AND LAMBERTON	<input type="checkbox"/>	Sound	4/27/2020/10:05 am	
15	SSO B CH-09 BRADFORD AND LEE	<input type="checkbox"/>	Not Sound	4/27/2020/12:36 pm	
Reset					
16	SSO B CH-10 HAMPSHIRE LANE AT MAYFIELD 18"	<input type="checkbox"/>	Sound	4/27/2020/ 9:05 am	
17	SSO B CH-11 HAMPSHIRE LANE AT MAYFIELD 36"	<input type="checkbox"/>	Sound	4/27/2020/ 9:07 am	
18	SSO B CH-13 HAMPSHIRE LANE AT EUCLID HTS. BLVD	<input type="checkbox"/>	Sound	4/27/2020/ 9:15 am	
19	SSO B CH-17 1685 CUMBERLAND	<input type="checkbox"/>	Sound	4/27/2020/ 8:58 am	
20	SSO B CH-22 2225 NOBLE ROAD	<input type="checkbox"/>	Sound	4/27/2020/ 8:20 am	
21	SSO B CH-25 CUMBERLAND AND SOMERTON	<input type="checkbox"/>	Sound	4/27/2020/ 8:55 am	
22	SSO B CH-26 EUCLID HTS. BLVD. AND CUMBERLAND	<input type="checkbox"/>	Sound	4/27/2020/ 8:50 am	
23	SSO B CH-27 QUILLIAMS AND RANDOLPH	<input type="checkbox"/>	Sound	4/27/2020/ 8:00 am	
24	SSO B CH-28 EUCLID HTS. BLVD. AND LEE RD.	<input type="checkbox"/>	Not Sound	4/27/2020/12:14 pm	
Need help to reset too dangerous					
25	SSO B CH-51 ATHERSTONE AND LANGTON	<input type="checkbox"/>	Sound	4/27/2020/ 8:15 am	
26	SSO C CH-12 LEE AND SUPERIOR	<input type="checkbox"/>	Sound	4/27/2020/12:19 pm	
27	SSO C CH-14 DERBYSHIRE AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/27/2020/ 9:25 am	
28	SSO C CH-15 COVENTRY AND CEDAR	<input type="checkbox"/>	Sound	4/27/2020/ 9:35 am	

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

29	SSO C CH-23 2828 BERKSHIRE EAST OF COVENTRY	<input type="checkbox"/>	Sound	4/27/2020/ 9:45 am	
30	SSO C CH-24 3003 EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/27/2020/ 9:50 am	
31	SSO C CH-30 SOUTH TAYLOR NORTH OF SUPERIOR	<input type="checkbox"/>	Sound	4/27/2020/10:35 am	
32	SSO C CH-42 12537 CEDAR ROAD	<input type="checkbox"/>	Sound	4/27/2020/ 9:30 am	
33	SSO C CH-46 EDGEHILL AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	4/27/2020/10:20 am	
34	SSO C CH-47 2528 STRATFORD	<input type="checkbox"/>	Sound	4/27/2020/10:10 am	
35	SSO C CH-52 EDDINGTON ROAD NORTH OF AVONDALE	<input type="checkbox"/>	Not Sound	4/27/2020/ 9:00 am	
Board is missing					
36	SSO C CH-54 2806 FAIRMOUNT	<input type="checkbox"/>	Sound	4/27/2020/ 1:55 pm	
37	SSO A CH-5 FAIRMOUNT AND SHELBURNE	<input type="checkbox"/>	Sound	4/27/2020/12:42 pm	
Eastbound					
38	SSO A CH- 6 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Sound	4/27/2020/12:46 pm	
Sidewalk Shelburne and Fairmount					
39	SSO A CH-07 FAIRMOUNT AT SHELBURNE	<input type="checkbox"/>	Sound	4/27/2020/12:53 pm	
Westbound lane					
40	SSO C CH-50 3293 FENLEY	<input type="checkbox"/>	Sound	4/27/2020/ 8:05 am	
41	SSO B CH-57 E MONMOUTH W OF DARTMOOR	<input type="checkbox"/>	Sound	4/27/2020/10:15 am	
42	SSO B CH-58 E MONMOUTH AT EXETER	<input type="checkbox"/>	Sound	4/27/2020/10:25 am	
43	SSO B CH-59 3427 THORNE RD	<input type="checkbox"/>	Sound	4/27/2020/ 8:30 am	
44	SSO B CH-60 3415 THORNE ROAD	<input type="checkbox"/>	Sound	4/27/2020/ 8:32 am	
45	SSO C CH-61 2600 HAMPSHIRE ROAD	<input type="checkbox"/>	Sound	4/27/2020/ 9:12 am	
46	SSO CH-56 MEADOWBROOK AND LEE	<input type="checkbox"/>	Sound	4/27/2020/ 9:40 am	4/27/2020

Tasks/Resources						
<b>SWCT26 Inspection</b>						
<b>Crew:</b>	<b>Status:</b>	<b>*Cal'c UC:</b> \$6.08	<b>*Task Cost:</b> \$279.52	<b>Start Dt:</b> 4/27/2020		
<b>Supervisor:</b>	<b>UOM:</b> Each	<b># of Units:</b> 46.00	<b>*Unit Cost:</b> \$0.00	<b>End Dt:</b>		
<b>Employee</b>						
<b>Resource</b>	<b>UOM</b>	<b>Units</b>	<b>*Total Cost</b>	<b>Alt Description</b>	<b>Start Dt</b>	<b>End Dt</b>
22394 Cardarella, Joe	Hours	8.00	\$172.32		4/27/2020	
<b>Equipment</b>						
<b>Resource</b>	<b>UOM</b>	<b>Units</b>	<b>*Total Cost</b>	<b>Alt Description</b>	<b>Start Dt</b>	<b>End Dt</b>
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		4/27/2020	
<b>Task Comment:</b> EXCESSIVE RAINFALL 0.60 INCHES OF RAIN						

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	107.20	0.00	0.00
Unit of Measure:		Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing	
<b>Billed Party</b>	
Customer ID:	Customer Number:
Customer Name:	Last Name:
Address:	
City:	Phone:
State:	Fax #:
Zip:	E-mail:
	Cell #:
<b>Billing Data</b>	
Contact Name:	*Billing Amount:
Invoice Number:	Date Bill Sent:
Incoming Account #:	Payment Received:
	Payment Method:
	Billing Required: <input type="checkbox"/>
	Billing Processed: <input type="checkbox"/>
	Imported to Financials: <input type="checkbox"/>

Associated PMs	
PM Code and Description	Closed
SSO-101 SSO INSPECTION FORM	<input checked="" type="checkbox"/>

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-101 - SSO INSPECTION FORM	jjackson	4/27/2020	7:45 AM
Supervisor Notification	Email Queued Successfully!	jjackson	4/27/2020	7:45 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	4/27/2020	7:46 AM

Rates:	Opened At:	Televised: <input type="checkbox"/>
Receieved By:	Pipe Footage Cleaned :	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>
Test Performed Throug	Appointment Date: 4/27/2020 7:30 AM	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	WO User 22:	

**Work Order Detail Report**

4/28/2020

SSO INSPECTION 4-27-2020 0.60 INCHES OF RAIN

10:37 AM

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slec
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/27/2020	PM Trigger:	Rec #: 5396

\* A 'Hidden' field indicates permission to view the secured field is turned off.